Ship Name: CRISTINA EXPRESS Ship Type: General Dry Cargo Ship

IMO Number: 7910199 Flag: Antigua and Barbuda

Date Detained: 07/30/2003 Class Society: Bureau Veritas

Port: Miami, Florida Company(s): Owners, Operators or Managers

Cristina Express Corp.

International Maritime Ships Agents Corp.

Deficiencies: Code - Category Description

0230 - Number/composition Vessel not manned in accordance with safe

(manning) Manning Document.

Ship Name: HIGHGATE Ship Type: Bulk Carrier

IMO Number: 8215560 Flag: United Kingdom

Date Detained: 07/08/2003 Class Society: Nippon Kaiji Kyokai

Port: San Juan, Puerto Rico Company(s): Owners, Operators or Managers

Satin Shipping Co.

Deficiencies: Code - Category Description

1730 - Oily-water separating Oily water separator inoperable.

Equipment

Ship Name: KEOYANG MAJESTY Ship Type: General Dry Cargo Ship

IMO Number: 9131072 Flag: Panama

Date Detained: 07/24/2003 Class Society: Korean Register of Shipping

Port: New Orleans, Louisiana Company(s): Owners, Operators or Managers

Keoyang Shipping Co. Ltd

GOA Leasing International S.A.

Deficiencies: <u>Code - Category</u>

2510 - Safety and environmental

policy

Description

An external audit of the Safety Management System is required by the Flag State or a recognized organization action on behalf of the Flag State. Objective evidence discovered through vessel's arrival and non-notification

of missing stbd anchor.

KEVSER Ship Type: General Dry Cargo Ship Ship Name:

IMO Number: 9037305 Flag: Malta

Date Detained: 07/08/2003 Class Society: **Bureau Veritas**

> Owners, Operators or Managers Port: New Orleans, Louisiana Company(s):

> > Seferroglu Denizcilik Ticaret ve Sanayi A.S.

TASE Shipping Co.

Deficiencies: Code - Category

0230 - Number/composition

(manning)

2510 - Safety and environmental

policy

Description

The vessel is not manned in accordance with

the safe manning certificate.

Objective evidence discovered in an expanded

ISM examination revealed that the

company/vessel has failed to fully implement the requirements of the ISM Code through the Safety Management System. External audit

required.

Ship Name: LA CRUISE Ship Type: Passenger Ship

IMO Number: 7716593 Flag: Panama

Class Society: Det Norske Veritas Date Detained: 07/21/2003

Port: Jacksonville, Florida Company(s): Owners, Operators or Managers

LA Cruise, Inc

H. Dewayne Williams

Deficiencies: Code - Category

0220 - Certificates of competency

Description

Safe Manning Document not complied with. Many of the required crew do not have flag

state endorsements nor documentary proof of

application.

MEXICO EXPRESS Ship Name: Ship Type: Containership

IMO Number: 9160504 Flag: Antigua and Barbuda

Class Society: Date Detained: 07/29/2003 **Bureau Veritas**

> Port: Jacksonville, Florida Company(s): Owners, Operators or Managers

Mar Consult Gesellshaft

Urraco Shipping Compnay Limited

Deficiencies: Code - Category Description

1430 - Auxiliary engines No. 3 ship's service generator inoperable due

to high pressure fuel pump leaking.

Ship Name: **POLYDINAMOS** Ship Type: Bulk Carrier

IMO Number: 7525841 Flag: Saint Vincent and the Grenadines

Date Detained: 07/11/2003 Class Society: **Russian Maritime Register of Shipping**

Port: New Orleans, Louisiana Company(s): Owners, Operators or Managers

> Bernuth Agencies, Inc. Olympic Chartering S.A.

Deficiencies: Code - Category Description

> 0230 - Number/composition The master of the vessel does not have a flag (manning)

state endorsement or documentary proof that

one was applied for.

Ship Name: **SANDINO BAY** Ship Type: Refrigerated Cargo Carrier

IMO Number: 8410902 Flag: Cyprus

Date Detained: 07/09/2003 Class Society: Nippon Kaiji Kyokai

Company(s): Owners, Operators or Managers Port: Dutch Harbor, Alaska

Ferolink Shipping Co. LTD.

Deficiencies: Code - Category Description

> 0610 - Lifeboats Starboard lifeboat engine inoperable.

0710 - Fire prevention Galley pass-throughs to two accommodation

spaces do not meet A-O bulkhead

0710 - Fire prevention Numerous fire boundaries compromised by

open cable pass-throughs installed for cable run from generator located outside on main

deck to main machinery space.

0745 - Fire-dampers remote

control, etc.

Multiple fire doors not functioning properly; several primary fire boundary doors had

inoperative latches preventing them from

remaining shut.

Ship Name: SUMMIT Ship Type: Passenger Ship

IMO Number: 8412467 Flag: Bahamas

Date Detained: 07/15/2003 Class Society: Lloyd's Register of Shipping

Port: Juneau, Alaska Company(s): Owners, Operators or Managers
Celebrity Cruises

Deficiencies: Code - Category Description

2555 - Documentation No evidence that audits were carried out and

crew unfamiliar with frequency of audits.

2540 - Emergency preparedness Electronic version of SMS in use not accessible to all crew who need to use SMS checklist.

ertification, verification SMS in use not approved by Issuing Authority.

2565 - Certification, verification

and control

2530 - Resources and Personnel SMS not accessible by CE and CE not familiar

with Casualty Checklists.

2520 - Designated person(s) Designated Person not known by ships crew

and not posted on ISM Placards.

2510 - Safety and environmental

policy

Objective evidence discovered in an expanded

ISM examination revealed that the

company/vessel has failed to implement the requirements of the ISM Code through the Safety Management System. External audit

requested.